

# TOLEDO CITY WATER DISTRICT

## PRODUCTION & MAINTENANCE DIVISION

### WATER QUALITY MONITORING REPORT

for the period : August 2018

#### II. CHLORINE RESIDUAL MONITORING POINTS

MONITORING POINTS	Sampling Source	Actual Ave Monthly Chlorine Residual	REMARKS
<b><u>NORTH SECTION (Dumlog-Mainggit)</u></b>			
1. Cluster near Talavera Brgy Hall	Faucet	0.8	Sodium Hypochlorite
2. Nearest cluster after Matab-ang tank	Cluster	0.7	Sodium Hypochlorite
3. Boundary Matab-ang/Mainggit	Cluster	1.1	Sodium Hypochlorite
<b><u>CENTRAL SECTION (Poblacion-Daanlungsod-Kabulihan)</u></b>			
1. Nearest cluster after Tubod steel tank	Faucet	0.8	Sodium Hypochlorite
2. Public Market	Faucet	0.6	Sodium Hypochlorite
3. Nearest cluster after Magsaysay Pump (TCH)	Faucet	0.7	Sodium Hypochlorite
4. Cluster near Nestor Yu Res	Faucet	0.4	Sodium Hypochlorite
5. Cluster after Luray I Pump (Gaisano Metro)	Faucet	0.7	Sodium Hypochlorite
6. End of Sangi Beach	Cluster	0.4	Sodium Hypochlorite
7. Nearest cluster after Ilihan Pump	Faucet	0.8	Sodium Hypochlorite
8. Dumlog after Sapang Daku Bridge	Faucet	0.3	Sodium Hypochlorite
<b><u>SOUTH SECTION (Ibo-Bato)</u></b>			
1. Cluster near Alqueza Res.	Faucet	1	Sodium Hypochlorite
2. Near Awihao National High School (Tomarong Res)	Cluster	0.6	Sodium Hypochlorite
3. Boundary Pinamungajan/Bato (across INC)	Cluster	0.6	Sodium Hypochlorite
4. Cluster near EXCEL Hardware	Cluster	0.6	Sodium Hypochlorite
5. Nearest cluster after Bitoon Pump	Cluster	0.6	Sodium Hypochlorite
6. Cluster near D. Pahaganas Res.	Cluster	0.4	Sodium Hypochlorite
<b><u>EAST SECTION (Cantabaco-Magdugo)</u></b>			
1. Cluster at Kabulihan 2	Faucet	0.4	Sodium Hypochlorite
2. Cluster near Magdugo Elem School	Cluster	0.4	Sodium Hypochlorite
3. Jose Maria Village	Faucet	0.6	Sodium Hypochlorite
4. QWMAA Cluster	Faucet	0.4	Sodium Hypochlorite
5. Das Village II	Faucet	0.6	Sodium Hypochlorite
6. ABSA Cluster	Faucet	0.6	Sodium Hypochlorite
7. Sibagay	Faucet	0.4	Sodium Hypochlorite
8. Bulongan Elem School	Cluster	0.7	Sodium Hypochlorite
<b>Total Sodium Hypochlorite</b>	<b>Ave</b>	<b>0.6</b>	

Monitoring Recorded By:

**MANUEL CANCELLER JR.**  
Water Resources Facilities Tech

Certified Correct:

**Carlito P. Lariosa**  
Water Sewerage Maintenance Head

Noted By:

**Ariel M. Abella**  
Acting Eng'g & Operation Dept. Head